

# CERTIFICATE OF COMPLIANCE

**Certificate Number** UL-US-2124817-0  
**Report Reference** E308660-20210506  
**Date** 15-May-2021

**Issued to:** Elko EP S R O  
PALACKEHO 493 HOLESOV-VSETULY  
Czech Republic 769 01

**This is to certify that representative samples of** NKCR - Auxiliary Devices  
See Addendum Page for Product Designation(s).

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

**Standard(s) for Safety:** UL 60947-1, 5th Ed., Issue Date: 2013-07-31, Revision Date: 2019-05-06, UL 60947-5-1, 3rd Ed., Issue Date: 2014-03-28

**Additional Information:** See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information

This Certificate of Compliance does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>




# CERTIFICATE OF COMPLIANCE

**Certificate Number** UL-US-2124817-0  
**Report Reference** E308660-20210506  
**Date** 15-May-2021

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

<b>Model</b>	<b>Category Description</b>
<b>DIN rail types</b> , CRM-111H, followed by UNI may be followed by suffixes.	Timing relays
<b>DIN rail types</b> , CRM-112H, followed by UNI may be followed by suffixes.	Timing relays
<b>DIN rail types</b> , CRM-113H, followed by UNI may be followed by suffixes.	Timing relays
<b>DIN rail types</b> , CRM-121H, followed by UNI may be followed by suffixes.	Timing relays
<b>DIN rail types</b> , CRM-131H, followed by UNI may be followed by suffixes.	Timing relays
<b>DIN rail types</b> , CRM-161, followed by UNI may be followed by suffixes.	Timing relays
<b>DIN rail types</b> , CRM-181J, followed by UNI may be followed by suffixes.	Timing relays
<b>DIN rail types</b> , CRM-182J, followed by UNI may be followed by suffixes.	Timing relays
<b>DIN rail types</b> , CRM-183J, followed by UNI may be followed by suffixes.	Timing relays
<b>DIN rail types</b> , CRM-2H, followed by UNI may be followed by suffixes.	Timing relays
<b>DIN rail types</b> , CRM-2T, followed by UNI may be followed by suffixes.	Timing relays
<b>DIN rail types</b> , CRM-91H, followed by UNI may be followed by suffixes.	Timing relays
<b>DIN rail types</b> , CRM-92H, followed by UNI may be followed by suffixes.	Timing relays
<b>DIN rail types</b> , CRM-93H, followed by UNI may be followed by suffixes.	Timing relays
<b>Plug-in types</b> , PTRM-216K, may be followed by suffixes.	Timing relays
<b>Plug-in types</b> , PTRM-216T, may be followed by suffixes.	Timing relays
<b>Plug-in types</b> , PTRM-216K, may be followed by suffixes.	Timing relays
<b>Plug-in types</b> , PTRM-216KP, may be followed by suffixes.	Timing relays
<b>Plug-in types</b> , PTRM-216T, may be followed by suffixes.	Timing relays
<b>Plug-in types</b> , PTRM-216TP, may be followed by suffixes.	Timing relays



Bruce Mahrenholz, Director North American Certification Program

UL LLC



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

# CERTIFICATE OF COMPLIANCE

**Certificate Number** UL-CA-2120362-0  
**Report Reference** E308660-20210506  
**Date** 15-May-2021

**Issued to:** Elko EP S R O  
PALACKEHO 493 HOLESOV-VSETULY  
Czech Republic 769 01

**This is to certify that representative samples of** NKCR7 - Auxiliary Devices Certified for Canada  
See Addendum Page for Product Designation(s).

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

**Standard(s) for Safety:** CSA C22.2 NO. 60947-1-13, 2nd Ed., Issue Date: 2013-07-31, CSA C22.2 NO. 60947-5-1-14, 1st Ed., Issue Date: 2014-03-01

**Additional Information:** See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information

This Certificate of Compliance does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>




# CERTIFICATE OF COMPLIANCE

**Certificate Number** UL-CA-2120362-0  
**Report Reference** E308660-20210506  
**Date** 15-May-2021

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

<b>Model</b>	<b>Category Description</b>
<b>DIN rail types</b> , CRM-111H, followed by UNI may be followed by suffixes.	Timing relays
<b>DIN rail types</b> , CRM-112H, followed by UNI may be followed by suffixes.	Timing relays
<b>DIN rail types</b> , CRM-113H, followed by UNI may be followed by suffixes.	Timing relays
<b>DIN rail types</b> , CRM-121H, followed by UNI may be followed by suffixes.	Timing relays
<b>DIN rail types</b> , CRM-131H, followed by UNI may be followed by suffixes.	Timing relays
<b>DIN rail types</b> , CRM-161, followed by UNI may be followed by suffixes.	Timing relays
<b>DIN rail types</b> , CRM-181J, followed by UNI may be followed by suffixes.	Timing relays
<b>DIN rail types</b> , CRM-182J, followed by UNI may be followed by suffixes.	Timing relays
<b>DIN rail types</b> , CRM-183J, followed by UNI may be followed by suffixes.	Timing relays
<b>DIN rail types</b> , CRM-2H, followed by UNI may be followed by suffixes.	Timing relays
<b>DIN rail types</b> , CRM-2T, followed by UNI may be followed by suffixes.	Timing relays
<b>DIN rail types</b> , CRM-91H, followed by UNI may be followed by suffixes.	Timing relays
<b>DIN rail types</b> , CRM-92H, followed by UNI may be followed by suffixes.	Timing relays
<b>DIN rail types</b> , CRM-93H, followed by UNI may be followed by suffixes.	Timing relays
<b>Plug-in types</b> , PTRM-216K, may be followed by suffixes.	Timing relays
<b>Plug-in types</b> , PTRM-216T, may be followed by suffixes.	Timing relays
<b>Plug-in types</b> , PTRM-216K, may be followed by suffixes.	Timing relays
<b>Plug-in types</b> , PTRM-216KP, may be followed by suffixes.	Timing relays
<b>Plug-in types</b> , PTRM-216T, may be followed by suffixes.	Timing relays
<b>Plug-in types</b> , PTRM-216TP, may be followed by suffixes.	Timing relays



Bruce Mahrenholz, Director North American Certification Program

UL LLC



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>